

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401445445

Receive Date:  
\_\_\_\_\_

Report taken by:  
\_\_\_\_\_

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	<b>Phone Numbers</b>
Address: <u>1775 SHERMAN STREET - STE 3000</u>		Phone: <u>(303) 860-5800</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>		Mobile: <u>( )</u>
Contact Person: <u>Karen Olson</u>	Email: <u>Karen.Olson@pdce.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

**PROJECT INFORMATION**

Remediation Project #: 10583 Initial Form 27 Document #: 401426513

**PURPOSE INFORMATION**

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

**SITE INFORMATION** N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>331001</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>MATT-64N67W 24NWSW</u>	Latitude: <u>40.295495</u>	Longitude: <u>-104.846403</u>	
	** correct Lat/Long if needed: Latitude: <u>40.294916</u>	Longitude: <u>-104.848228</u>	
QtrQtr: <u>NWSW</u>	Sec: <u>24</u>	Twp: <u>4N</u>	Range: <u>67W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

**SITE CONDITIONS**

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Riparian

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

**Other Potential Receptors within 1/4 mile**

Occupied housing is located approximately 1,065 feet south of the tank battery location. Surface water is located approximately 1,775 feet southeast of the tank battery location. The nearest water well is located approximately 550 feet east of the tank battery location.

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             |  |
| <input type="checkbox"/> Oil                       | <input type="checkbox"/> Tank Bottoms                |  |
| <input checked="" type="checkbox"/> Condensate     | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) |  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	Refer to Supplemental Form 19.	Completion of vacuum recovery events and sampling.
No	SOILS	Refer to Supplemental Form 19.	Completion of excavation and sampling.

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On February 20, 2014, a historic release was discovered below the production tanks during the plug and abandonment of the Matt #1 facility (API # 05-123-20011). On May 6, 2014, a Form 19 was submitted to the COGCC under Document No. 400603164 and the release was issued Spill No. 437089. Between February 20 and February 24, 2014, approximately 180 cubic yards of impacted material were removed and transported to the North Weld Landfill in Ault, Colorado under PDC waste manifests. Based on the analytical results from the confirmation soil and groundwater sampling conducted following mitigation efforts, a Form 27 No Further Action (NFA) request was submitted to the COGCC via email on May 13, 2014.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Per landowner concerns and as requested by the COGCC, excavation activities will be conducted below the former PDC production tanks. Following excavation activities, four (4) discrete soil samples will be collected from the sidewalls of the final excavation extent. Soil samples will be collected above the capillary fringe within the unsaturated interval. Soil samples will be submitted to Summit Scientific Laboratories (Summit) in Golden, Colorado for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) - gasoline range organics (GRO) by United States Environmental Protection Agency (USEPA) Method 8260B, and TPH - diesel organics range (DRO) by USEPA Method 8015. Analytical results for the soil samples collected from the final extent of the excavation will be compared with the applicable COGCC Table 910-1 standards.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

PDC anticipates that groundwater will be encountered within the excavation at approximately 5.5 to 6 feet below ground surface (bgs). Following excavation activities, one groundwater sample will be collected from the excavation and submitted to Summit Scientific Laboratories (Summit) in Golden, Colorado for analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX) by United States Environmental Protection Agency (USEPA) Method 8260B. Analytical results for the groundwater sample collected from the excavation will be compared with the applicable COGCC Table 910-1 groundwater standards.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 5  
Number of soil samples exceeding 910-1 1  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 625

### NA / ND

-- Highest concentration of TPH (mg/kg) 3900  
NA Highest concentration of SAR           
BTEX > 910-1 No  
Vertical Extent > 910-1 (in feet) 6

### Groundwater

Number of groundwater samples collected 2  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 6'  
Number of groundwater monitoring wells installed 0  
Number of groundwater samples exceeding 910-1 1

-- Highest concentration of Benzene (µg/l) 4.9  
-- Highest concentration of Toluene (µg/l) 29  
-- Highest concentration of Ethylbenzene (µg/l) 400  
-- Highest concentration of Xylene (µg/l) 7400  
NA Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected  
0 Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 180      Volume of liquid waste (barrels) 350

Is further site investigation required?

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Between October 19 and October 23, 2017, approximately 530 cubic yards of impacted material were removed and transported to West Connections Front Range landfill in Erie, Colorado for disposal under PDC waste manifests.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Between October 19 and October 23, 2017, eight (8) soil samples (SS01 - SS07, and SS09) were collected from the sidewalls of the final excavation extent at depths ranging between 5 feet and 6.5 feet below ground surface (bgs). Additionally, two (2) soil samples (North Test Pit and East Test Pit) were collected from test pits excavated north and east (down-gradient) of the excavation area at approximately 6 feet bgs. The samples were submitted to Summit Scientific Laboratories (Summit) in Golden, Colorado for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) - gasoline range organics (GRO) by United States Environmental Protection Agency (USEPA) Method 8260B, and TPH - diesel range organics (DRO) by USEPA Method 8015. Analytical results indicated that constituent concentrations were below applicable COGCC Table 910-1 standards in all soil sample locations. Groundwater was encountered within the excavation at approximately 6 feet bgs. Following the completion of excavation activities, approximately 2,520 barrels of groundwater were removed via vacuum truck and transported to a licensed disposal facility. On October 27, 2017, one groundwater sample (PitGW01) was collected from the excavation and submitted to Summit for laboratory analysis of BTEX by USEPA Method 8260B. Analytical results indicated that BTEX concentrations were not detected at or above laboratory reporting limits and below applicable COGCC Table 910-1 groundwater standards. Based on the analytical results, PDC is requesting a No Further Action (NFA) determination for this site.

## Soil Remediation Summary

In Situ

Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

Yes \_\_\_\_\_ Excavate and offsite disposal

\_\_\_\_\_ Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 530

\_\_\_\_\_ Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Excavate and onsite remediation

\_\_\_\_\_ Other \_\_\_\_\_

\_\_\_\_\_ Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater analytical data collected during excavation activities indicated that dissolved-phase hydrocarbon impacts were not present on site. Therefore, groundwater monitoring is not required.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

**Frequency:**  Quarterly  Semi-Annually  Annually  Other No Further Action Request

**Report Type:**  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other No Further Action Request

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use.

Volume of E&P Waste (solid) in cubic yards 530

E&P waste (solid) description Non-hazardous E&P exempt waste.

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: North Weld Waste Management Facility.

Volume of E&P Waste (liquid) in barrels 2520

E&P waste (liquid) description Groundwater

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: Licensed disposal facility.

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? No

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following the completion of excavation activities, the excavation will be backfilled and re-contoured to match pre-existing conditions. The area will be reclaimed in accordance with COGCC Rule 1004.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

# IMPLEMENTATION SCHEDULE

## PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

## SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/20/2014

Date of commencement of Site Investigation. 02/20/2014

Date of completion of Site Investigation. 10/27/2017

## REMEDIAL ACTION DATES

Date of commencement of Remediation. 02/20/2014

Date of completion of Remediation. 10/27/2017

## SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

## OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Karen Olson

Title: Senior EHS Manager

Submit Date: \_\_\_\_\_

Email: Karen.Olson@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 10583

## COA Type

## Description

--	--

## Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

### Att Doc Num

### Name

401448905	ANALYTICAL RESULTS
-----------	--------------------

Total Attach: 1 Files

## General Comments

### User Group

### Comment

### Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)