



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing within the interim reclamation areas and comprised of species such as western wheatgrass (*Pascopyrum smithii*) and big squirreltail (*Elymus multisetus*).**





**Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Diversion ditch appears to be functioning.**





**Photo 4. View of stabilized soil stockpile in the northern portion of the project area.**