

Inspection Photos
Location Name: PASCO SPADAFORA #2
Location ID: 413893



Photo 1. Hatches open on unused tanks.



Photo 2. Incorrect signage on unused tanks.

Inspection Photos
Location Name: PASCO SPADAFORA #2
Location ID: 413893



Photo 3. Location photos with tanks on three sides.



Photo 4. Incorrect signage on unused tanks.