

Inspection Photos
Location Name: Federal 11-90-15
Location ID: 324491



Photo 1. Label has peeled off chemical container.



Photo 2. Chemical container stored on edge of location.

Inspection Photos
Location Name: Federal 11-90-15
Location ID: 324491



Photo 3. Frack tanks with no labels and containment not maintained.



Photo 4. Open end tanks not labeled with tracking to sawdust pile.

Inspection Photos
Location Name: Federal 11-90-15
Location ID: 324491



Photo 5. Saw dust with tracking to open end tanks..



Photo 6. Hatches open at time of inspection.

Inspection Photos
Location Name: Federal 11-90-15
Location ID: 324491



Photo 7. No sign at wellhead.



Photo 8. No sign at wellhead. Staining on wellhead and in cellar.

Inspection Photos
Location Name: Federal 11-90-15
Location ID: 324491



Photo 9. Trash along edge of location.



Photo 10. Stored machinery on location.