

Inspection Photos  
Well Name: MCINTYRE 11-90-14 1  
Location ID: 324474



Photo 1. Wood and metal banding trash.



Photo 2. trash near tanks.