

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



11.01.2017 14:49

**Photo 1 Location photo**

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



11.01.2017 14:50

**Photo 2 Weeds on pad**

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



11.01.2017 14:54

**Photo 3 unmarked Dead man**

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



11.01.2017 14:59

**Photo 4 Stored equipment**

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



**Photo 5 Debris incorporated with fill**

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



11.01.2017 15:05

**Photo 6 Unused risers**

Inspection Photos  
Location Name DGU Federal 1289  
Section 18 Pad



**Photo 7 Unused riser**