

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2017

Submitted Date:

11/01/2017

Document Number:

689100090**FIELD INSPECTION FORM**
 Loc ID 312540 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10144Name of Operator: XOG OPERATING LLCAddress: P O BOX 352City: MIDLAND State: TX Zip: 79702**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	NW Region, Engineer
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Conklin, Curtis		curtis.conklin@state.co.us	Field Inspector, NW
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Crawford, Angie		acrawford@xogoperating.com	XOG
Colby, Lou		lou.colby@state.co.us	Reclamation Inspector, NW

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
312540	LOCATION	AC			-	WELLS-69S103W 16NWSE	EI

General Comment:

Joint inspection with Reclamation Specialist Lou Colby and Field Inspector Curtis Conklin. This inspection focused specifically on environmental aspects. XOG has removed all equipment, a tank included. Only the wellhead and some conductors remain. No signs of staining, spill or stress vegetation were observed. No signs of pit either. A desktop review showed no indication that a pit had ever existed. Aerial photos (see attached) indicate that an open top tank was located approximately 60 feet NE of the well. Before final reclamation, the operator shall take a confirmation sample from the tank footprint to ensure compliance with Table 910-1.

Inspected FacilitiesFacility ID: 312540 Type: LOCATION API Number: - Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
Before final reclamation, the operator shall take a confirmation sample from the tank footprint to ensure compliance with Table 910-1.	lujanc	11/01/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689100091	Photo Report XOG Wells 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293486