

Inspection Photos  
Location Name: Walker 3-4  
API: 05-081-07098



**Photo 1. Overview of location taken at entrance facing northeast.**