

MERRION OIL & GAS CORP – 56680
API # 05-113-06051 COCKLEBUR DRAW UNIT #1
Inspection Date : 10/23/2017



Sign shows API# as 05-113-06228.
Should be 05-113-06051



Weeds around fired equipment



Weeds inside tank berms



Weeds inside tank berms



Multiple abandoned risers not locked out/tagged out or marked for abandonment.



Unused equipment-Dehydrator and Glycol Reboiler



Reboiler water line disconnected from tank.



Abandoned risers not locked out/tagged out or marked for abandonment.



Tank berms before corrective action. Picture taken 11/3/2016



Tank berms after corrective action. Picture taken 10/23/2017



Trash and junk before corrective action. Picture taken 11/3/2016



Trash and junk removed after corrective action. Picture taken 10/23/2017



Chemical drums with secondary containment.
Picture taken 10/23/2017



Chemical drums with secondary containment.
Picture taken 10/23/2017