

- Hugus Federal 1 05-033-06076



Photo 1: Wellhead sign. Previous inspection.

- Hugus Federal 1 05-033-06076



Photo 2: Location overview. Follow-up inspection.

- Hugus Federal 1 05-033-06076



Photo 3: Wellhead with production tree removed. Riser painted orange.

- Hugus Federal 1 05-033-06076



Photo 4: Wellhead with risers removed. Follow-up inspection.

- Hugus Federal 1 05-033-06076



Photo 5: Unmarked deadman. Previous inspection.

- Hugus Federal 1 05-033-06076



Photo 6: Anchors marked.

- Hugus Federal 1 05-033-06076



Photo 7: Disconnected separator and stack in NW corner of location.

- Hugus Federal 1 05-033-06076



Photo 8: Separator removed from NW corner. Follow-up inspection.

- Hugus Federal 1 05-033-06076



Photo 7: Risers where separator had been.

- Hugus Federal 1 05-033-06076



Photo 8: Cleaned up area where separator had been. Gas meter run and flowlines removed. Follow-up inspection.