

- Ranger Federal #11 - 18
- 05-033-06079



Photo 1: Wellhead sign. Previous inspection.

- Ranger Federal #11 - 18
- 05-033-06079



Photo 2: Wellhead sign. Follow-up inspection.

- Ranger Federal #11 - 18
- 05-033-06079



**Photo 3: Impacted soil and gravel around base of wellhead.**

- Ranger Federal #11 - 18
- 05-033-06079



**Photo 4: Wellhead with impacted soil cleaned up and leak repaired. Follow-up inspection.**

- Ranger Federal #11 - 18
- 05-033-06079



**Photo 5: Abandoned flowline on S side of gas meter run building.**

- Ranger Federal #11 - 18
- 05-033-06079



**Photo 6: Removed flowline. Follow-up inspection.**



- Ranger Federal #11 - 18
- 05-033-06079



**Photo 7: Separator with cleaned up berms. Follow-up inspection.**

- Ranger Federal #11 - 18
- 05-033-06079



**Photo 8: Location overview. Follow-up inspection.**