

- Parker 21 – 31 05-067-09197



Photo 1: Wellhead sign. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 2: Wellhead sign. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 3: Wellhead. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 4: Wellhead. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 5: Wood pallets and debris. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 6: Removed debris. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 7: Rolled fencing. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 8: Rolled fencing. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 9: Unused riser beside bermed area. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 10: Removed risers and berms. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 11: Production related trash at wellhead. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 12: Removed trash at wellhead. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 13: No longer in use bermed area. Previous inspection.

- Parker 21 – 31 05-067-09197



Photo 14: Cleaned up area where equipment berms had been. Follow-up inspection.

- Parker 21 – 31 05-067-09197



**Photo 15: Wider view of location and Thistle on location.
Previous inspection.**

- Parker 21 – 31 05-067-09197



Photo 16: Marked anchor and location overview.

- Parker 21 – 31 05-067-09197



Photo 17: Marked anchor and location overview. Follow-up inspection.

- Parker 21 – 31 05-067-09197



Photo 18: Marked anchor and location overview.