

Inspection Photos
Location Name: Grynberg State 6-36
API: 05-081-06751



Photo 1. Overview of location taken at entrance facing north. Tubing and portapotty visible on location.