

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2017

Submitted Date:

11/07/2017

Document Number:

689500336

FIELD INSPECTION FORM

Loc ID 336042 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: PO BOX 6501
City: ENGLEWOOD State: CO Zip: 80155

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296064	WELL	PR	06/01/2013	GW	103-11290	FREEDOM UNIT 297-16A1	PR
296065	WELL	SI	07/01/2017	GW	103-11289	FRFREEDOM UNIT 297-16A5	SI
296066	WELL	PR	06/01/2013	GW	103-11288	FREEDOM UNIT 297-16A4	PR
296067	WELL	PR	06/01/2013	GW	103-11287	FREEDOM UNIT 297-16A2	PR
296068	WELL	PR	06/01/2013	GW	103-11286	FREEDOM UNIT 297-16A3	SI
296069	WELL	PR	06/01/2013	GW	103-11285	FREEDOM UNIT 297-16A6	PR
296070	WELL	SI	02/01/2017	GW	103-11284	FREEDOM UNIT 297-16A10	PR
296071	WELL	PR	06/01/2013	GW	103-11283	FREEDOM UNIT 297-16A7	SI
296072	WELL	PR	06/01/2013	GW	103-11282	FREEDOM UNIT 297-16A8	PR
296073	WELL	PR	07/01/2013	GW	103-11281	FREEDOM UNIT 297-16A9	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:
 Comment:
 Corrective Action:
 Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	Central separator		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	296064	Type:	WELL	API Number:	103-11290	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pr - via plunger lift - no leaks/venting				Corrective Action:		Date:		
Facility ID:	296065	Type:	WELL	API Number:	103-11289	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE						
Comment:	Well Si - no leaks/venting - production records indicate well has produced with in the last 2 yrs				Corrective Action:		Date:		
Facility ID:	296066	Type:	WELL	API Number:	103-11288	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pr - via plunger lift - no leaks/venting				Corrective Action:		Date:		
Facility ID:	296067	Type:	WELL	API Number:	103-11287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pr - via plunger lift - no leaks/venting				Corrective Action:		Date:		
Facility ID:	296068	Type:	WELL	API Number:	103-11286	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE						
Comment:	Well Si - no leaks/venting - production records indicate well has produced with in the last 2 yrs				Corrective Action:		Date:		
Facility ID:	296069	Type:	WELL	API Number:	103-11285	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pr - via plunger lift - no leaks/venting				Corrective Action:		Date:		
Facility ID:	296070	Type:	WELL	API Number:	103-11284	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Pr - via plunger lift - no leaks/venting				Corrective Action:		Date:		
Facility ID:	296071	Type:	WELL	API Number:	103-11283	Status:	PR	Insp. Status:	SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well Si - no leaks/venting - production records indicate well has produced with in the last 2 yrs

Corrective Action: _____ Date: _____

Facility ID: 296072 Type: WELL API Number: 103-11282 Status: PR Insp. Status: PR

Producing Well

Comment: Pr - via plunger lift - no leaks/venting

Corrective Action: _____ Date: _____

Facility ID: 296073 Type: WELL API Number: 103-11281 Status: PR Insp. Status: PR

Producing Well

Comment: Pr - via plunger lift - no leaks/venting

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
Retention Ponds	Pass					
Compaction	Pass					

Comment: No sediment flow evident

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500337	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4296869