

Inspection Photos
Well Name: Henderson 1R
Location ID: 324477



Photo 3. Unused pump jack.



Photo 4. Unmarked anchors on edge of location.