

Construction and Stormwater Inspection

November 3, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP - #26580

Location ID: 451166

Adams County, CO

NESE Section 35 T3S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Big Sandy 3-65 36-31 /2CH
Location ID: 451166



Photo 1. Photo taken from the entrance of location, facing South. Tracking pad device has been installed.



Photo 2. Photo taken from the northeastern location, facing North. Sediment trap is IN-PROCESS of being constructed. A temporary filter wattle BMP has been installed around the perimeter of the location.

Inspection Photos

Location Name: Big Sandy 3-65 36-31 /2CH

Location ID: 451166



Photo 3. Photo taken from the northeastern location, facing South. Operator has installed a temporary filter. A wattle BMP has been installed around the perimeter of the location.



Photo 4. Photo taken from the eastern location. Photo illustrates the wattle BMP has been overlapped at the joints and properly staked.

Inspection Photos
Location Name: Big Sandy 3-65 36-31 /2CH
Location ID: 451166



Photo 5. Photo taken from the eastern location, facing South. Topsoil salvage operations are IN-PROCESS.



Photo 6. Photo taken from the southern location, facing West. See comments under Photo 3.

Inspection Photos

Location Name: Big Sandy 3-65 36-31 /2CH

Location ID: 451166



Photo 7. Photo taken from the southern location, facing West towards the topsoil stockpile. Appears the Operator is storing topsoil along the southern location.



Photo 8. Photo taken from the southwestern location, facing North. See comments under Photo 3.