

# Final Reclamation and Stormwater Inspection

November 3, 2017

Operator: PETROSHARE CORPORATION- 10454

Location ID: 382086

Elbert County, CO

SESE Section 19 T6S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: RMPCO-EVERETT-UPRR #1

Location ID: 382086



**Photo 1.** Google Earth aerial imagery taken 9/29/1999 illustrating well and battery location during operations.

## Inspection Photos

Location Name: RMPCO-EVERETT-UPRR #1

Location ID: 382086



**Photo 2.** Google Earth aerial imagery taken 6/15/2010 illustrating well and battery location after the location was plugged in 2003. Both the well and battery locations do not meet Rule 1004 standards. COGCC staff does not have photos of the battery location because it was not known until after the inspection that the battery location was Petroshare's. However, COGCC staff recalls there was a List B Colorado noxious weed, Diffuse knapweed (*Centaurea diffusa*), throughout the battery location, in addition to stormwater erosion issues.

Inspection Photos  
Location Name: RMPCO-EVERETT-UPRR #1  
Location ID: 382086



**Photo 3.** Photo taken of the eastern well location, facing East. Operator has not reclaimed the location per Rule 1004 standards. The location has not been contoured to match the surrounding landscape. Rill erosion evident along the eastern cut slope.



**Photo 4.** Photo taken from the northeast well location, facing East. See comments under Photo 3.

Inspection Photos  
Location Name: RMPCO-EVERETT-UPRR #1  
Location ID: 382086



**Photo 5.** Photo taken from the eastern well location, facing South. See comments under Photo 3.



**Photo 6.** Photo taken from the eastern well location, facing North. See comments under Photo 3.