

Inspection Photos

11/09/2017

Operator: CASCADE PETROLEUM LLC - 10414

Location ID: 439341

Inspection Doc. Number: 682502781

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: CASCADE PETROLEUM LLC - 10414
Location ID: 439341



Photo 1: Photo of sign at location entrance.



Photo 2: Photo taken from the southwest end of the location, facing west. Inspection #682502556 required operator to install or repair stormwater and sediment control BMPs on location. Photo shows hay-bale ponding BMP that has not been maintained or repaired, and is not in proper functioning condition.



Photo 3: Photo taken from the southwest end of the location, facing north. Photo shows straw wattle ponding BMPs on location. Photo also shows areas where water movement has created gully erosion



Photo 4: Photo taken from the straw wattle BMP at top of photo 3 (green arrow). Photo shows BMP is not longer in proper functioning condition as stormwater has cut under the wattle.



Photo 5: Photo taken from the southwest southwest end of the location. Inspection #682502556 required operator to repair erosion and stabilize the location. Photo shows erosion degradation has not been repaired, and stabilized. Hat for reference.



Photo 6: Photo taken from the south end of the location, facing southwest. Photo shows straw wattle ponding BMPs on location.