

Inspection Photos
Location Name: Lion #2
API: 05-123-12877



Photo 1: Location, looking SW



Photo 2: Wellhead, looking E

Inspection Photos
Location Name: Lion #2
API: 05-123-12877



Photo from J Gomez's inspection for comparison purposes



Photo 3: Stained soil removed, leak fixed

Inspection Photos
Location Name: Lion #2
API: 05-123-12877



Photo 4: Damage on berm



Photo 4: Low spot in berm