



**Photo 1. View from the approximate northeastern corner of the reclaimed well pad facing center.**



**Photo 2. View of the northern portion of the reclaimed well pad from the northeastern corner facing westward. Revegetation is progressing with grasses and forbs such as orchardgrass (*Dactylis glomerata*), clovers (*Trifolium* spp.), and alfalfa (*Medicago sativa*).**



**Photo 3. View of the eastern portion of the reclaimed well pad from the northeastern corner facing southward.**



**Photo 4. View of Russian knapweeds (*Acroptilon repens*) within the central portion of the reclaimed well pad.**



**Photo 5. View of concentrated Russian knapweed within the reclaimed well pad area.**



**Photo 6. Birdseye view of vegetation east of the former project area. Dense knapweed not present.**



**Photo 7. View of representative reference area east of the project area. Concentrated Russian knapweed as observed within the reclaimed well pad area not present.**