

Inspection Photos
Location Name: Kortum #7
API: 05-001-06190



Risers not marked



Valve leaking on treater