

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



1. Location north looking south 11/8/2017



2. Pumping unit & VGS covered with vegetation 11/8/2017

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



3. Water tank without berms 11/8/2017



4. Inadequate wildlife netting 11/8/2017

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



5. Inadequate wildlife netting, Fluid in tank 11/8/2017



6. Meter shed with Lease sign 11/8/2017

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



7. Chemical tank without containment (BMP) 11/8/2017