

**Inspection Photos**  
**Location Name: Cogburn 1-1**  
**API: 05-009-06551**



**1. Sign at Entrance covered with weeds**



**2. Access covered with vegetation**



Inspection Photos  
Location Name: Cogburn 1-1  
API: 05-009-06551



3. Meter shed and vertical gas separator



4. Electronic meter run

**Inspection Photos**  
**Location Name: Cogburn 1-1**  
**API: 05-009-06551**



**5. Pumping unit and debris**



**6. Weeds and debris across location**



**Inspection Photos**  
**Location Name: Cogburn 1-1**  
**API: 05-009-06551**



**7. Debris, unused parts**



**8. Weeds, debris and unused parts**

**Inspection Photos**  
**Location Name: Cogburn 1-1**  
**API: 05-009-06551**



**9. Open top water tank with no berms**



**10. Water tank damaged and leaking**

**Inspection Photos**  
**Location Name: Cogburn 1-1**  
**API: 05-009-06551**



**11. Inadequate wildlife netting with fluid in tank**



**Incapable of producing in present state. Power supply cut off**