

Inspection Photos

11/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 327317

Inspection Doc. Number: 682502797
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 327317



Photo 1: Photo taken from the northwest end of the location, facing south. Photo shows pipe riser has been removed and additional reclamation work appears to have been conducted.



Photo 2: Photo taken from the access road, facing west. Photo shows reclamation work on access road.