

Inspection Photos

11/14/2017

Operator: BARRETT RESOURCES CORP - 6495 /
WPX

Location ID: 327317

Inspection Doc. Number: 682502799

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: BARRETT RESOURCES CORP - 6495 / WPX

Location ID: 327317



Photo 1: Photo taken from the former battery location. Photo shows pipe riser equipment has been removed per the CA.