

Inspection Photos

11/14/2017

Operator: Noble Energy

Location ID: 327317

Inspection Doc. Number: 682502799

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: Noble Energy
Location ID: 327317



Photo 1: Photo taken from the south end of the well, facing north. Photo shows riser and disturbance due to re-plugging efforts from Noble. Upon formal abandonment of the well, Noble will be required to reclaim the location in accordance to COGCC 1000 series reclamation rules and requirements.



Photo 2: Photo taken from the south end of the well, facing northeast. Photo shows riser and disturbance due to re-plugging efforts from Noble. Upon formal abandonment of the well, Noble will be required to reclaim the location in accordance to COGCC 1000 series reclamation rules and requirements.

Inspection Photos
Operator: Noble Energy
Location ID: 327317



Photo 3: Photo taken from the east end of the well, facing west. Photo shows riser and disturbance due to re-plugging efforts from Noble. Upon formal abandonment of the well, Noble will be required to reclaim the location in accordance to COGCC 1000 series reclamation rules and requirements.



Photo 4: Photo taken from adjacent reference area. Photo shows vegetation over the reference area. Vegetation seen here predominantly Sand Dropseed, Western Wheatgrass, etc..



Photo 1: Photo taken from the former battery location. Photo shows pipe riser equipment has been removed per the CA.