

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2017

Submitted Date:

11/17/2017

Document Number:

689400648

**FIELD INSPECTION FORM**

Loc ID 336045 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 6301 DEAUVILLE BLVD  
City: MIDLAND State: TX Zip: 79706

**Findings:**

20 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name    | Phone          | Email                | Comment                         |
|-----------------|----------------|----------------------|---------------------------------|
| Grubbs, Richard | (970) 257-6021 | rtgrubbs@chevron.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 290195      | WELL | PR     | 09/27/2008  | GW         | 045-14036 | SKR 598-35-AV-06 | PR          |
| 291484      | WELL | PR     | 02/03/2008  | GW         | 045-14389 | SKR 598-35-AV-13 | PR          |
| 291485      | WELL | PR     | 05/22/2012  | GW         | 045-14390 | SKR 598-35-AV-11 | PR          |
| 291486      | WELL | TA     | 07/07/2015  | GW         | 045-14391 | SKR 598-35-AV-12 | TA          |
| 291487      | WELL | PR     | 10/30/2008  | GW         | 045-14392 | SKR 598-35-AV-14 | PR          |
| 291488      | WELL | PR     | 04/30/2009  | GW         | 045-14393 | SKR 598-35-AV-18 | PR          |
| 291489      | WELL | PR     | 02/29/2008  | GW         | 045-14394 | SKR 598-35-AV-02 | PR          |
| 291490      | WELL | PR     | 10/03/2008  | GW         | 045-14395 | SKR 598-35-AV-08 | PR          |
| 291491      | WELL | PR     | 07/20/2007  | GW         | 045-14396 | SKR 598-35-AV-15 | PR          |
| 291492      | WELL | PR     | 06/22/2009  | GW         | 045-14397 | SKR 598-35-AV-17 | PR          |
| 291494      | WELL | PR     | 05/08/2009  | GW         | 045-14400 | SKR 598-35-AV-09 | PR          |
| 291495      | WELL | PR     | 02/14/2008  | GW         | 045-14401 | SKR 598-35-AV-03 | PR          |
| 291496      | WELL | PR     | 02/22/2008  | GW         | 045-14402 | SKR 598-35-AV-01 | PR          |
| 291497      | WELL | PR     | 06/01/2015  | GW         | 045-14403 | SKR 598-35-AV-05 | PR          |
| 291498      | WELL | PR     | 05/15/2009  | GW         | 045-14404 | SKR 598-35-AV-07 | PR          |
| 291499      | WELL | PR     | 11/07/2008  | GW         | 045-14405 | SKR 598-35-AV-04 | PR          |
| 291500      | WELL | WO     | 11/17/2015  | GW         | 045-14406 | SKR 598-35-AV-10 | TA          |

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: [Emergency contact number posted. 877-257-6007](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Tanks and Berms:**

| Contents       | # | Capacity | Type      | Tank ID | SE GPS |
|----------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST |         |        |

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Paint**

Condition Adequate

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

|      |  |  |
|------|--|--|
| Type |  |  |
|------|--|--|

|                    |       |  |
|--------------------|-------|--|
| Comment:           |       |  |
| Corrective Action: | Date: |  |

| Inspected Facilities  |  |   |                 |             |           |         |    |               |    |
|-----------------------|--|---|-----------------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 290195   | Type:   | WELL            | API Number: | 045-14036 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |   |                 |             |           |         |    |               |    |
| Comment:              | Plunger  |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291484   | Type:   | WELL            | API Number: | 045-14389 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |   |                 |             |           |         |    |               |    |
| Comment:              | Plunger  |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291485   | Type:   | WELL            | API Number: | 045-14390 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |   |                 |             |           |         |    |               |    |
| Comment:              | Plunger  |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291486   | Type:   | WELL            | API Number: | 045-14391 | Status: | TA | Insp. Status: | TA |
| <b>Idle Well</b>      |  |   |                 |             |           |         |    |               |    |
| Purpose:              | <input type="checkbox"/> Shut In   | <input checked="" type="checkbox"/> Temporarily Abandoned | Reminder: _____ |             |           |         |    |               |    |
| Comment:              | Annual form 4 Doc#401400418 in process for continued TA status. Last MIT was 10/21/14. |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291487   | Type:   | WELL            | API Number: | 045-14392 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |   |                 |             |           |         |    |               |    |
| Comment:              | Plunger  |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291488   | Type:   | WELL            | API Number: | 045-14393 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |   |                 |             |           |         |    |               |    |
| Comment:              | Plunger  |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291489   | Type:   | WELL            | API Number: | 045-14394 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |   |                 |             |           |         |    |               |    |
| Comment:              | Plunger  |   |                 |             |           |         |    |               |    |
| Corrective Action:    |  |   |                 |             | Date:     |         |    |               |    |
| Facility ID:          | 291490   | Type:   | WELL            | API Number: | 045-14395 | Status: | PR | Insp. Status: | PR |

|                       |           |         |      |
|-----------------------|-----------|---------|------|
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291491    | Type:   | WELL |
| API Number:           | 045-14396 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291492    | Type:   | WELL |
| API Number:           | 045-14397 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291494    | Type:   | WELL |
| API Number:           | 045-14400 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291495    | Type:   | WELL |
| API Number:           | 045-14401 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291496    | Type:   | WELL |
| API Number:           | 045-14402 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291497    | Type:   | WELL |
| API Number:           | 045-14403 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291498    | Type:   | WELL |
| API Number:           | 045-14404 | Status: | PR   |
| Insp. Status:         | PR        |         |      |
| <b>Producing Well</b> |           |         |      |
| Comment:              | Plunger   |         |      |
| Corrective Action:    |           | Date:   |      |
| Facility ID:          | 291499    | Type:   | WELL |
| API Number:           | 045-14405 | Status: | PR   |
| Insp. Status:         | PR        |         |      |

**Producing Well**

Comment: [Plunger](#)

Corrective Action:

Date:

Facility ID: 291500 Type: WELL API Number: 045-14406 Status: WO Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: [Annual form 4 Doc#401400414 in process for continued TA status. Last MIT was 5/28/15.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            | Compaction              | Pass                  |               |                          |         |
| Compaction       | Pass            | Gravel                  | Pass                  |               |                          |         |
| Rip Rap          | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 689400649    | SKR-598-35-AV | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4304933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4304933</a> |