

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Schmidt #2 well head.



Schmidt #2 production equipment.

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Pit netting and supports stored along NE edge of location.



Pit liner stored near excavated area.

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Excavated condensate pit area.



Excavation of Pit Facility ID #112977.

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Schmidt #2 location photo.



Material stored in SW corner of location.