

Inspection Photos
Location Name: Wagner #A-2
API: 05-123-08850



Photo 1: Wellhead, looking NW



Inspection Photos
Location Name: Wagner #A-2
API: 05-123-08850



Photo from prior inspection for comparison



Photo 2: Stained soil removed

Inspection Photos
Location Name: Wagner #A-2
API: 05-123-08850



Photo from prior inspection for comparison



Photo 3: Stained soil removed

