

Inspection Photos
Location Name: Simmons A #1
API: 05-067-07861



Simmons A #1 well head.



Partially buried PW vessel.

Inspection Photos
Location Name: Simmons A #1
API: 05-067-07861



Water from irrigation ditch flowing along edge of location.



Soil gas survey being conducted around PA marker on location.