

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2017

Submitted Date:

11/20/2017

Document Number:

679903472**FIELD INSPECTION FORM**

Loc ID 321664 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207720	WELL	PR	08/01/2017	OW	017-06655	ARAPAHOE UNIT 139 (43-27)	PR

**General Comment:**

Routine Inspection

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Stickers on chemical tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 320		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Ford 300-6 cylinder motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Cathodic rectifier, day drum, gas scrubber, chemical drum w/containment		
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	207720	Type:	WELL	API Number:	017-06655	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (AU 139, 140, 141, 144, 145 INJ WELL, 180) 4250' NW @ 38.812810/-102.101720								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT