

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2017

Submitted Date:

11/20/2017

Document Number:

679903477**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
321676 \_\_\_\_\_ Welsh, Brian \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207744	WELL	PR	10/30/1990	OW	017-06679	ARAPAHOE UNIT 150 (41-28)	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by oil tanks		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 4		
Comment:	Electric panel, cathodic rectifier, chemical tank w/containment, telemetry equipment at battery		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 228		
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:	Treater with metal shed	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.812960,-102.112390
Comment:	Water tank is on east side of location				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.812920,-102.112880
Comment:	Oil tanks on west side of location				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 207744	Type: WELL	API Number: 017-06679	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing. Tank battery is 650' north on south side of CR Q			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT