

Photo#1:  
View North over Location Center



Photo#2:  
View South over Location Center  
Note debris weeds within 25Ft of Well Head area.



October 30, 2017

Photo#3:  
View East over Location Center



Photo#4:  
View West over Location Center




October 30, 2017

Photo#5:

Weeds that when dead, break off, blow and become Debris are on Location & within 25Ft of Well Head (also Cheat Grass).



Photo#6:



October 30, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: XOG Chaffin Loc#312502