

Inspection Photos
Location Name: Robioux 13-12-89-1
API: 05-081-06986



Photo 1. Overview of location taken at entrance facing west.

Inspection Photos
Location Name: Robidoux 13-12-89-1
API: 05-081-06986



Photo 2. Separator stored on location.



Photo 3. Shed and seacan in background, miscellaneous parts in foreground.