

# Final Reclamation Inspection

November 22, 2017

Operator: ENERGY SEARCH CO ADBA ENERGY  
SEARCH CO INC - 27635

API: 05-001-07287

Adams County, CO

NENW Section 20 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GINTHER #1  
API: 05-001-07287



**Photo 1.** Photo taken from the approximate PA well location, facing South. Final land use might be housing development as housing development construction activities are in-process nearby. The access road and location have not been reclaimed. There are pipe and various other debris which remains at location. See Photo 4 for an aerial photo for more information.

Inspection Photos  
Location Name: GINTHER #1  
API: 05-001-07287



**Photo 2.** Photo taken from the approximate PA well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: GINTHER #1  
API: 05-001-07287



**Photo 3.** Photo taken from the approximate PA well location, facing Northeast. See comments under Photo 1.



**Photo 4.** Aerial photo taken using COGCC GISOnline database illustrating well location in relation to new housing development.