

Photo#1:

View along Access Road into Location and Road into Storage area at North of Site.



November 3, 2017

Photo#2:

View from Storage area to South over lower Portion of Location. .



November 3, 2017

Photo#3:

Photo#4:

Interim Reclamation has been installed on Lower portion of Location



November 3, 2017

Photo#5:

Blanket / Netting has become Debris at Storage area of Location.



Photo#6:



November 3, 2017