

Inspection Photos
Location Name: Ritchey 26 Pad
Facility ID # 450193



Photo 1. Signs at entrance



Photo 2. Wells looking SE

Inspection Photos
Location Name: Ritchey 26 Pad
Facility ID # 450193



Photo 3. Location looking SW from NE corner of location



Photo 4. Location looking south from NE corner of location

Inspection Photos
Location Name: Ritchey 26 Pad
Facility ID # 450193



Photo 5. ECD and tanks looking SE



Photo 6. Tanks looking south

Inspection Photos
Location Name: Ritchey 26 Pad
Facility ID # 450193



Photo 7. Separators and VRU looking west



Photo 8. East side of separators and VRU looking west