

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2017

Submitted Date:

11/27/2017

Document Number:

666804060

FIELD INSPECTION FORM

Loc ID 334672 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|---|--------------------------|
| Elsener, Garrett | | COGCC.inspections@caerus oilandgas.com | All Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 267914 | WELL | PR | 01/07/2008 | GW | 045-09217 | GMR 4-15 (K4B) | PR |
| 267915 | WELL | SI | 05/01/2017 | GW | 045-09218 | GMR 4-11D (K4B) | SI |
| 267916 | WELL | PR | 10/31/2003 | GW | 045-09219 | GMR 4-14 (K4B) | PR |
| 267917 | WELL | PR | 01/07/2008 | GW | 045-09220 | GMR 4-14D (K4B) | PR |

General Comment:

Follow up inspection
 Action required items noted on previous inspection have been satisfied

| Inspected Facilities | | | | | | | | | |
|-----------------------|---------------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID: | <u>267914</u> | Type: | <u>WELL</u> | API Number: | <u>045-09217</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Plunger lift</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>267915</u> | Type: | <u>WELL</u> | API Number: | <u>045-09218</u> | Status: | <u>SI</u> | Insp. Status: | <u>SI</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Plunger lift</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>267916</u> | Type: | <u>WELL</u> | API Number: | <u>045-09219</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Plunger lift</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>267917</u> | Type: | <u>WELL</u> | API Number: | <u>045-09220</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Plunger lift</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |