



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of erosion occurring where concentrated stormwater flows off of the southeastern portion of the project area.



Photo 5. View of Canada thistles (*Cirsium arvense*) growing in a stand of western wheatgrass (*Pascopyrum smithii*) in the eastern portion of the project area.