

Photo#1:

View over Location Center to South.



November 13, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana Trail Ridge PA API#045-06998

Photo#2:

Desirable Vegetation is well established..



November 13, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana Trail Ridge PA API#045-06998

Photo#3:

Noxious weed, Houndstongue and thistle established on Location.



November 13, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana Trail Ridge PA API#045-06998

Photo#4:

Photo#5:

Gates are down at Location



November 13, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana Trail Ridge PA API#045-06998