

Inspection Photos

Location Name: Kori J 19-10

API #: 05-123-17994

Location ID: 329886



Wellhead looking south. Weeds need to be controlled



Battery looking north

