

Inspection Photos
Wells Name: DeBeque 8-3
Location ID: 312644



Photo 1. Vegetation debris around heated separator unit.



Photo 2. Vegetation around wellhead.

Inspection Photos
Wells Name: DeBeque 8-3
Location ID: 312644



Photo 3. Vegetation debris in tank containment.



Photo 4. Capacity not legible on produced water tank.