

Inspection Photos  
Wells Name: OXBOW 18-1E  
Location ID: 312634



**Photo 1. Pit used for tank containment.**



**Photo 2. Halogeton, Class C Noxious weed, along access road.**