

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2017

Submitted Date:

12/01/2017

Document Number:

666804101**FIELD INSPECTION FORM**
 Loc ID 334578 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                                     | Comment                                  |
|------------------|-------|---|--|
| Elsener, Garrett |       | COGCC.inspections@caerus<br>oilandgas.com | <a href="#">All Piceance inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------------|-------------|
| 89073       | WELL | SI     | 01/01/2017  | GW         | 045-07403 | MILLER 11-7                          | SI          |
| 272959      | WELL | PR     | 03/25/2005  | GW         | 045-10200 | CEDAR SPRINGS RANCH<br>11-3C (G11W)  | PR          |
| 272961      | WELL | PR     | 03/21/2005  | GW         | 045-10199 | CEDAR SPRINGS RANCH<br>11-11A (G11W) | PR          |
| 272963      | WELL | PR     | 03/22/2005  | GW         | 045-10197 | CEDAR SPRINGS RANCH<br>11-11B (G11W) | PR          |

**General Comment:**[Routine inspection](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Type: Gas Meter Run               | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Vertical Heated Separator   | # 3 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

| Contents           | #                   | Capacity | Type      | Tank ID | SE GPS |  |
|--------------------|---------------------|----------|-----------|---------|--------|--|
| METHANOL           | 1                   | 1000 GAL | STEEL AST |         | ,      |  |
| Comment:           | Centralized battery |          |           |         |        |  |
| Corrective Action: |                     |          |           |         | Date:  |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |   |                     |           |                     |         |                       |       |  |
|--------------------|----------|---|---------------------|-----------|---------------------|---------|-----------------------|-------|--|
| Type               | Capacity |   | Permeability (Wall) |           | Permeability (Base) |         | Maintenance           |       |  |
|                    |          |   |                     |           |                     |         |                       |       |  |
| Comment:           |          |   |                     |           |                     |         |                       |       |  |
| Corrective Action: |          |   |                     |           |                     |         |                       | Date: |  |
| Contents           |          | # | Capacity            | Type      |                     | Tank ID | SE GPS                |       |  |
| CONDENSATE         |          | 3 | 300 BBLS            | STEEL AST |                     |         | 39.461020,-107.740443 |       |  |
| Comment:           |          |   |                     |           |                     |         |                       |       |  |

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Corrective Action: |          | Date:               |                     |             |
| <b>Paint</b>       |          |                     |                     |             |
| Condition          | Adequate |                     |                     |             |
| Other (Content)    |          |                     |                     |             |
| Other (Capacity)   |          |                     |                     |             |
| Other (Type)       |          |                     |                     |             |
| <b>Berms</b>       |          |                     |                     |             |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |
| <b>Venting:</b>    |          |                     |                     |             |
| Yes/No             | NO       |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |
| <b>Flaring:</b>    |          |                     |                     |             |
| Type               |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |

**Inspected Facilities**

Facility ID: 89073 Type: WELL API Number: 045-07403 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last posted production numbers Nov. 2016

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 272959 Type: WELL API Number: 045-10200 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 272961 Type: WELL API Number: 045-10199 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 272963 Type: WELL API Number: 045-10197 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Gravel                  | Pass                  |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Rip Rap          | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
|                  |                 | Culverts                | Pass                  |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
| Seeding          | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 666804102    | caerus      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4315643">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4315643</a> |