

GV 47-35
Api# 05-045-06651
Inspection # 689700680



Location from east view.

GV 47-35
Api# 05-045-06651
Inspection # 689700680



W 24-35 from east view.

GV 47-35
Api# 05-045-06651
Inspection # 689700680



North view of tanks. Tanks anchored with cables and ground anchors.

GV 47-35
Api# 05-045-06651
Inspection # 689700680



Tanks anchored with cables and ground anchors.

Tanks anchored with cables and ground anchors.

GV 47-35
Api# 05-045-06651
Inspection # 689700680



South view of Separators are anchored with cables and ground anchors.



North view of Separators are anchored with cables and ground anchors.