

Inspection Photos
Location Name: Schroeder 33-32
API: 05-081-07131



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Unused risers not marked or LOTO.

Inspection Photos
Location Name: Schroeder 33-32
API: 05-081-07131



**Photo 3. Unused risers not marked or LOTO.
Equipment stored within deadmen perimeter.**



Photo 4. Equipment stored within deadmen perimeter.