

Inspection Photos
Location Name: Great Divide Federal 11-33
API: 05-081-07401



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Stained soil in berm.

Inspection Photos
Location Name: Great Divide Federal 11-33
API: 05-081-07401



Photo 3. Water and stained soil in berm.



Photo 4. Stained soil in berm.