

# Inspection Photos

Location Name: Foundation

API 045-06200

11/28/2017



**Former Pit looking West**



**Active pit looking Northwest**





**Debris from former pit**



**Empty carboys along Baxter Pass Road**