

Inspection Photos
Location Name: McCallum Unit 83
API: 05-057-06144



Photo 1. Overview of location taken at entrance facing northwest.