

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2017

Submitted Date:

12/01/2017

Document Number:

679903513**FIELD INSPECTION FORM**

Loc ID 321231 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 61650Name of Operator: MURFIN DRILLING COMPANY INCAddress: 250 N WATER ST STE 300City: WICHITA State: KS Zip: 67202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Esquivel, James	620-272-4913	j280189@pld.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206401	WELL	SI	09/01/2017	GW	011-06148	TEMPEL 1-13	WK

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Two track along west side of canal		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Lease sign at meter run		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign mounted to stairs at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on water tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Wire panels around tank and HGS		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: Location around wellhead is farmed. Tank battery is next to canal on west side

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT